






Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- 5.5 Hex Nutdriver
- Plier or cross


STEP 1




STEP 2




STEP 3



STEP 3



STEP 4



(1)	BH M3x10	C-3003-30-10
(2)	BH M3x18	C-3003-30-18
(3)	BH M3x14	C-3003-30-14

STEP 5

