






Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- Thread-locker 
- Lithium Grease 


STEP 1




STEP 2



STEP 3




STEP 4




Wing is not shown for clarity.


STEP 5



STEP 6



STEP 7



STEP 8

