




Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- Thread-locker 


Finish Before:

- Motor Mount (Up to step 3)
- Servo/Receiver Box (Step 2 and 4)




VIDEO MANUAL
ON YOUTUBE


STEP 1



STEP 2



STEP 3



STEP 4

