





### Required Tools:

- 2.0 Hex Driver
- Thread-locker 


### Finish Before:

- Center Gearbox / Motor Mount

### STEP 1



### STEP 2



### STEP 3

