






Required Tools:

- 1.5 Hex Driver
- 2.0 Hex Driver
- 2.5 Hex Driver
- Thread-locker 
- Lithium Grease 


STEP 1




STEP 2






STEP 3



- | | | |
|-----|----------|--------------|
| (1) | BH M3x12 | C-3003-30-12 |
| (2) | BH M3x14 | C-3003-30-14 |



STEP 4

STEP 5

STEP 6

STEP 7
