






Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- Thread-locker 
- Lithium Grease 


STEP 1



STEP 2




STEP 3




Wing is not shown for clarity.


STEP 4



STEP 5



STEP 6



STEP 7

