



STEP 51


B14(P)




STEP 01




STEP 02






STEP 05




STEP 06


Q46.A
+
Q46.B




STEP 07





STEP 08





STEP 09



STEP 10





STEP 11



STEP 12





B16(P)




STEP 13

R

B15(P)




STEP 14






R

B15(P)




STEP 15



R






STEP 16





STEP 01




STEP 02



STEP 03



STEP 04



STEP 05

