





Required Tools:


- 2.0 Hex Driver
- 2.5 Hex driver
- Shock Pliers
- Thread-locker 

STEP 1




 Manually turn the steering full right or full left to gain the access to the screws.

STEP 2



L=R

STEP 3



L=R