






Required Tools:

- 2.0 Hex Driver
- Cross wrench
- 5.5 Nut Driver
- Lithium Grease 


STEP 1




STEP 2




STEP 3



STEP 4



STEP 5



STEP 6

