






Required Tools:

- 2.0 Hex Driver
- 5.5 Nut Driver



STEP 1




STEP 2




STEP 3




STEP 4



STEP 5



STEP 6




L=R



Wing is not show for clarity.

STEP 7



STEP 8

