




Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- 7.0 Hex Nutdriver


Important Notice:

Wing is not shown for clarity.


Finish Before:

- Wheelie bar
- Skid Plate (Step 2-3)


STEP 1



STEP 2



STEP 3



STEP 4

