




STEP 04





STEP 05




STEP 06





STEP 07





STEP 08





STEP 09




STEP 10




STEP 11





STEP 12





STEP 13





STEP 14



STEP 15





STEP 16





STEP 17

Q29.A





STEP 18

Q27.B




STEP 19




STEP 20





ø0.5mm






ø0.5mm




STEP 21





STEP 22




STEP 23




528



STEP 24



STEP 25



STEP 26

