





Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- Shock Pliers
- Thread-locker 




VIDEO MANUAL
ON YOUTUBE

STEP 1




STEP 2



L=R

STEP 3



L=R