


Required Tools:


- 2.0 Hex Driver
- 2.5 Hex Driver
- Thread-locker 



VIDEO MANUAL
ON YOUTUBE

STEP 1

BH M3x6
C-3003-30-06




STEP 2

FH M4x20
C-3002-40-20

C-00180-882

FH M4x16
C-3002-40-16

M4 FH Washer
C-3213-40-5



STEP 3

C-00180-880

FH M4x12
C-3002-40-12

