





Required Tools:

- 2.0 Hex Driver
- 2.5 Hex Driver
- Thread-locker 


Finish Before:

- Servo / Receiver Box


STEP 1



STEP 2



STEP 3



STEP 4

